

INSTALLATION INSTRUCTIONS


For

HAND BRAKE SIGNAL LAMP — OH-18159

LINCOLN MERCURY

DIVISION OF FORD MOTOR COMPANY

DETROIT - MICHIGAN



INSTRUCTIONS FOR INSTALLING HAND BRAKE SIGNAL LAMP

- (1) - RELEASE BRAKE AND TURN OFF IGNITION.
- (2) - DRILL 3/16" DIA. HOLE BY PANEL AS SHOWN.
- (3) - LEAVE LEFT PANEL ON SIDE W/IGN. ASSY. INSERT BULB SOCKET INTO DRILLED HOLE FROM BALL SIDE OF PANEL. SNAP LEADS ON TO BULB SOCKET AND SECURE BY PRESSING INTO DRILLED HOLE.
- (4) - CONNECT TERMINAL TO IGNITION SWITCH AS SHOWN.
- (5) - REMOVE BULB FROM BULB SOCKET AND CLIP OVER FRONT TUBE OF SOCKET.
- (6) - PLACE BRACKET AND OH-18159 BRACKET ASSY AS SHOWN. TURN ON IGNITION. WHERE BULB DOES NOT LIGHT FROM POINT WHERE LIGHT TURNS ON, THEY TIGHTEN BRACKET UNTIL SECURELY.
- (7) - IF BULB DOES NOT LIGHT FROM POINT WHERE LIGHT TURNS ON, THEY TIGHTEN BRACKET UNTIL SECURELY. IF IT FAILS TO LIGHT, THEY TIGHTEN BRACKET UNTIL IT IS CLEAR OF CONTACT POINTS.
- (8) - PLACE BULB IN SOCKET WHEN HAND BRAKE IS PULLED SET THE IGNITION SWITCH IS ON.

MERCURY INSTALLATION